

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Page 1 of 6

Reason For Inspection:

Predicted Precipitation Source:

1st Weekly

2nd Weekly

		s.									DATE:	1-17-12
State Roule	(SR) / US Rout	le or Road Nar	me and Des	scription:			Are correctiv	e actions r	equired by II	his inspec	tion report (Y/N):	
	Wolf River Blvd.								No	1		
County(ies):		TDOT PIN:	1	VPDES Peri	nil (NOC) #	I:	Number of N	ew	Number of R	Recurring	Number of New	Number of Un-Corrected
Sh	elby	10161	5	T	NR 153299		Corrective A	clions:	Corrective A	clions:	Sediment Releases:	Sediment Releases:
TDOT Const	ruction No.:	TDOT Contrac	i No.:	Contractor:			0		0			
7994 - 1	1535-54			Aculf I	Enterprises	Inc.						
												
I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information. I certify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as recorded in the table above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment to knowing violations.					m luated who g the ulfalls) and the table a of the order as alties for somment for	Contractor COG EPS (print or ty	EPSC Inspe C Project Ma pe):	d "Jerry" S color and T	tanfill itle (print or t	lype):	Signature: Signature: Signature:	Starfiel Ballace
		_TDOT EPSC	Inspection Rainfall	n Weekly R Rainfall	Rainfall Dat	a Log Rainfall	Rainfall	Rainfall			htractor Agrees with	Inspection Report:
Date	Day of Week	Precipitation (%)	Gauge 1 (in)	Gauge 2 (in)	Gauge 3 (in)	Gauge 4 (in)	Gauge 5 (in)	Gauge 6 (in)		NO If No, exp	or YES olain and initial:	
	Sunday	1.57	77	(1.7	N/A	N/A	N/A	N/A				
1.16.12	Monday	40			N/A	N/A	N/A	N/A				
1.17.12	Tuesday	40 30	0	0	N/A	N/A	N/A	N/A				
1.18.12	Wednesday	0.			" N/A	N/A	N/A	N/A				
1.19.12	- Thursday	- 0			N/A	N/A	N/A	N/A				
1.20.12	Friday	30			N/A	N/A	N/A	N/A				
1.20.12	Salurday	0			N/A	N/A	N/A	N/A				
1.15.12	Sunday	0			N/A	N/A	N/A	N/A				
	Monday				N/A	N/A	N/A	N/A	-14	l.		

'www.weather.com

State/US	Route	or R	oad i	Name:
----------	-------	------	-------	-------

Wolf River Blvd.

TDOT Construction No.:

195		

TDOT	Contract No.:	
------	---------------	--

Date 1/17/2012			
	Date	1/17/2012	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	1/17/2012	30.00	22,35	FM	Monitoring outfall.
1A	1	21+50	RT	1/17/2012		41	FM	Const. of RCBC Pedestrian Underpass in progress.
1B	1	22+00	RT	1/6/2011		41	S	Currently stable, monitoing BMP's
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	s	Currently stable, monitoing BMP's
2A	1	33+50	LT,CL	1/17/2012		12,15,16	s	Currently stable, monitoing BMP's
2B	1	35+50	LT	1/17/2012		16,24	FM	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	FM	Outfall slopes north of temp. stream crossing are showing signs of failure.
4	1	40+00	RT	12/12/2011	T = 10-24-11	15,16,43	S	Currently stable at this time.
5A	1	49+00	RT	1/6/201		16,33	S	Currently stable, monitoring BMP's
5B	1	50+00	RT	12/19/2011		9,16,33	s	Currently stable, monitoing BMP's

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Excess Dirt Removed from Rdwy. Daily Temporary seeding with Mulch Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch Haul Roads Dampened for Dust Control 30 Upgrade Needed (Failure Noted) Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure **Enhanced Silt Fence** Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling CM Corrections currently being made 13 Geotextile Preserve Natural Resource / Buffer Zone 27 Haul Road 41 Other (O31): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 **Bridge Construction** Other (O#2): Stream Realignment Other (O#3):

CONDITION CODES

	OF.	THE	57	
185	AGRI	CUL	LURE	
	15	*	7	
		796	33	1.

State/US Route or Road Name:	٧
------------------------------	---

Nolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT Contract No .:

Date	1/17/2012	
		_

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	1/12/2012	1 - 1 cim.	16,24,33	CM,FM	1) Corrections are required on all rills and washouts at bank slopes of unnamed channel. 2) SFB is needed on north top bank slope. 3) Weekly cleaning for stream crossing required.
6	1	56+00	LT	1/17/2012			FM	Fill material being installed in pond during inspection.
7	1	60+00	RT	10/24/2011		16, 33	S	Currently stable, monitoring BMP's.
8A	1	73+00	RT	1/17/2012		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,35,41	FM	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	1/17/2012		16,35,42	S	Bridge construction zone. Monitoring BMP's.
8D	2	75+50	LT	1/17/2012	T = 10-3-11	16,35,42	СМ	Bridge 2, Abutment 2 at north corner and bank slopes require stabilization.
8E	1	71+50	LT		10.0 00			The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	S	Currently stable, monitoring BMP's.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	S	Currently stable, monitoring BMP's.

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch

Temporary Diversion Berm or Ditch 16 Temporary Mulch Temporary Slope Drain 17 **Erosion Control Blanket**

- Rock Check Dams Flexible Channel Liner 18 5 **Brush Barrier** 19
- 6 Sediment Removal 20 Riprap Outlet Structure
- 7 Straw Bale Check 21
- 8 Sand Bags 9
- Sediment Trap / Basin
- Temp Sediment Filter Bag / Dewatering 10 11 Polyethylene Sheeting
- 12 Machined Rip Rap
- 13 Geotextile
- Permanent Seeding with Mulch or Sod

EROSION AND SEDIMENT CONTROL MEASURE CODES

29 Excess Dirt Removed from Rdwy. Daily Haul Roads Dampened for Dust Control 31 Ditch Liner 32 Rock Silt Screen

- Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing 34 Enhanced Silt Fence
- Riprap Energy / Velocity Dissipater 22 Curb, Gutter, or Storm Sewer Protection 36 23 Temporary at Construction Exit / Entrance
- 24 Temporary Stream Crossing 25 Turbidity Barrier / Silt Boom
- 26 Temporary Stream Diversion 27 Preserve Natural Resource / Buffer Zone 28 Mineral Aggregate Base on Subgrade
- Sediment Tube Sediment Dam 37 Concrete Washout, other pollution Issues 38 Berm (soil, riprap, rock) 39 Gabion 40 Sheet Pilling 41 Haul Road Other (O31):

Bridge Construction

CONDITION CODES Maintenance

141	Mantenance
U	Upgrade Needed (Failure Noted)
R	Replacement Needed
FM	Future Maintenance

- Cleaning Needed Increase Measures
- W Too Wet to Work Conditions Repeat Occurrence
- SR Sediment Release FS Final Stabilized
- Stable (No Action Needed) CM Corrections currently being made

Other	(O#2):
Other	(O#3): -

2

3

2	total	/1 10	Pau	100	r Daad	Name:
J	laic	-	1 \Uu	CO	Nuau	ivallie.

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT Contract No.:

Date 1/17/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	S	Currently stable, monitoring BMP's.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Repairs will be needed after job site dries out Note: Too wet to install structural backfill
10B	2	85+00	RT	9/29/2011	150.	15,16,35,41	FM	Repairs will be needed after job site dries out Note: Too wet to install structural backfill
10C	2	85+50	LT	11/14/2011		15,16,35,41	FM	Repairs will be needed after job site dries out Note: Too wet to install structural backfill
10D	2	84+50	LT	1/6/2012		15,16,35,41	s	Currently stable, monitoring BMP's.
11A	2	92+50	RT	11/14/2011		35,41	S	Repairs will be needed after job site dries out Note: Too wet to install structural backfill
11B	2	92+50	LT	1/6/2012		10,32,35,41	S	Currently stable, monitoring BMP's.
11C	2	92+00	LT	10/6/2011		10,32,35,41	S	Currently stable, monitoring BMP's.
	1	11+28	LT	1/17/2012		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	1/17/2012		23,29,30	FM	Daily cleaning will be required, until further notice.
	11	107+75 EROSIO	CL N AND SEDIME	1/17/2012 NT CONTROL N	MEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen Future Maintenance **Brush Barrier** 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence 34 Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater Sediment Tube 35 Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Slable (No Action Needed) 12 Machined Rip Rap 26 Sheet Pilling Temporary Stream Diversion 40 CM Corrections currently being made 13 Geolextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): Permanent Seeding with Mulch or Sod 14 Mineral Aggregate Base on Subgrade 42 Bridge Construction Other (O#2):

Other (O#3):

State/US Route or Ro

ate/US Route or Road Name:	Wolf River Blvd.

TDOT	Construction	NIa
111/1/1	Consudencion	INU

7	^	-	_	4	_	-	~	-	-	4

TDOT C	ontract No.:	
--------	--------------	--

Date	1/17/2012	

S			ar root variet		Date of	Existing				
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current			
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments		
(Existing	No.	From / To			T = Temp.	Measure	Codes			
Structure)			-		P = Perm.	Codes*				
* 400 54						\$00.00 (COC) (COC) (COC)	2000-0000000	Daily cleaning will be required, until further		
* 109+51	2	East side of WRB	RT	1/17/2012		19,22	FM	notice.		
	_	South side of				N		Daily cleaning will be required, until further		
* 109+11	2	Farmington	RT	1/17/2012		19,22	FM	notice.		
		North side of		400 CO CONT. A MARKATA CONTRACTOR CONTRACTOR				Daily cleaning will be required, until further		
* 12+80	1	WRB	LT	1/17/2012		19,22	FM	notice.		
		Walking Trail					33.31			
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	S	Currently stable, monitoring BMP's		
						10.77				
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	S	Currently stable.		
		Sta. 13+40 -						Haul roads dampened frequently for dust		
		Sta. 107+75	LT, RT or CL	10/13/2011		30	S	control, until further notice.		
					300000					
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	S	Currently stable, monitoring BMP's		
						AND MADE AND A				
	22	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	S	Currently stable, monitoring BMP's		
	14	2 12						Daily cleaning will be required, until further		
	1	6+75	LT	1/17/2012		19,22	FM	notice.		
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	s	Currently stable, monitoring BMP's		
		Section Control of the Control of th						Tanana, monitoring Divil		
	1	34+00	RT	8/25/2011	T= 8-25-11	16	S	Currently stable, monitoring BMP's		
	EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITION CODES									

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	l	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

EPSC Inspection

	OFTHE	**.
(8)	24	
EA	AGRICULT	URE
	1776	

0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date _____1/17/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	S	Currently stable, monitoring BMP's.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	S	Currently stable, monitoring BMP's.
	1	25+00	LT	12/14/2011	T = 10-6-11	15,16,33,35,41	S	Currently stable at this time.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	S	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	S	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	S	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	S	Currently stable, monitoring BMP's.
* 108+37		North side of WRB	LT	1/17/2012		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	S	Currently stable, monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1 Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy, Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):

CONDITION CODES